

Release Notes for RISA-3D

Version 23.0.0 Enhancements/Corrections

- General:
 - Updated installers to support Remote Mass Deployment through tools such as Microsoft Intune.
 - Updated Telerik .NET libraries to the latest versions to address security vulnerabilities.
- Design:
 - Added ASCE 7-22 / IBC 2024 Load Combination generation.
 - Added Wind and Seismic loads generation per ASCE 7-22.
 - Added design Response Spectra per ASCE 7-22.
 - Added member design per the AISC 360-22 (16th edition) steel specification.
 - Corrected Sy calculation for hot-rolled steel double angle shapes when using CSA codes.
- Integration:
 - Added a note in the RISACONNECTION anchorage Detail Report indicating seismic load combinations were imported from RISA-3D and seismic provisions were not considered.
 - Resolved an issue where RISACONNECTION integration did not select the correct column when columns shared a node with a beam.
 - Corrected an error message to read 'Invalid member type' instead of 'Invalid connection member shape' to more accurately reflect the cause of the issue.
 - Fixed an issue where column splice integrations to RISACONNECTION incorrectly used member end forces from the incorrect column instead of consistently taking them from the physically top column.
 - Changed behavior so that a Continuous Beam over Column connection assigned at the bottom of a column in RISA-3D does not transfer to RISACONNECTION.
 - Fixed an issue where HSS T-Connection tube orientations were incorrect for connections integrated to RISACONNECTION.
 - Corrected the graphical representation of HSS T connections by updating the moment direction to align with the applied load orientation in RISA-3D.
 - Fixed an integration issue to RISACONNECTION where identical connections with different labels were incorrectly grouped under a single label or assigned the wrong label in newly created models.
 - Fixed an issue where, in rare cases, incorrect shear load transfer occurred for diagonal brace connections during integration to RISACONNECTION, resulting in inconsistent beam end forces.
 - Fixed an issue where, in rare cases, Diagonal Vertical Brace Connections failed to integrate to RISACONNECTION due to incorrect beam orientation detection caused by short beam length.
- Printing/Reports:
 - Fixed an issue where the units in data exported from the Time History Trace dialog did not match the model's specified units.

- Detail Report:
 - Corrected a typo in the Cold Formed Steel (CFS) Detail Report where the area unit was shown as ksi.
- Aluminum:
 - Fixed an issue where user-specified section properties (Z_{zz} , Z_{yy}) for aluminum shapes were not applied in design.