

Release Notes for RISA-2D

Version 21.0 Enhancements/Corrections

- General:
 - Corrected an issue where the 'Save As' function was not working properly.
 - Resolved an issue where the search functionality within the F1 help dialog was not functioning as expected.
 - Converted to cloud-based subscription licensing.
- Wood:
 - Updated SGAF factor display in detailed report for wood walls with perforated and FTAO methods.
 - Resolved an issue where the US region default file used CAN SIMPSON hold downs.
 - Corrected a rare issue that would incorrectly calculate the wall sheathing shear ratio check.
- Interface/Graphics:
 - Fixed an issue when opening certain older model files, the display of the LC list may be empty.
 - Resolved an issue where the program has a blank icon in the Windows Uninstaller list.
- Hot Rolled Steel:
 - Corrected a false warning messages about missing XML files when launching the program
- Concrete:
 - Fixed an issue where the controlling LC may not be reported correctly under Envelope solution for concrete members.